




**INSTALLATION TO COFFEE MACHINE (STEAM WAND)**

**INSTALLATION NOTE:**

POWER-IN CABLE & PURGE-OUT LINE  
CAN BE RUN ON TOP OF BENCH TO  
COFFEE MACHINE BENCHTOP HOLE.  
OTHERWISE Ø65 HOLE REQUIRED TO  
RUN CABLE & LINE UNDER BENCH.



Installer to ensure burst sleeve  
is covering all exposed metal  
surfaces from the Legato point  
of steam connection.